

**MAINTENANCE CAR REPAIR RECORDS** *Mileage 62156*

**VEHICLE #** 3B  
**YEAR** 2008  
**TYPE** Activity Bus  
**COLOR** White

**LOCATION** North  
**LICENSE #** M170330  
**VIN #** 1GBJG31K081159807

Service Date	Mileage	Repair Description	Part #	Cost	Comments
9/12/2014	36109	6 new tires		769.87	mounting
9/22/2014	36561	found ABS senser bad replace rt. Front hub assy.			
9/30/2014	38950	Service xxx and change the air filter and wipers			lane test.
9/11/2015	41957	complete unit and outside screen		776.26	unit, screen ok at this time
10/20/2015	42353	state vehicle inspection , and install new tailpipe		61.95	Midas did the work
1/19/2016	43656	Service xxx check and fill all fluids levels			
4/14/2016	44502	take to safety lane for 6 mo test			30 was out.
10/25/2016	47762	take to safety lane for 6 mo test			
11/10/2016	47628	one, I also did a service xxx and air filter			
10/18/2017	51366	side door handle on .			42 someone broke the lock to get in
10/30/2017	51400	work , I took to bill kay , and they did rear brake		941.16	hardware
10/23/2018	57099	rear door weather strip			safety lane test
1/24/2019	57753	intalled a left hub wheel bearing assy.	hub,27102189	213	
10/25/2019	62065	Service xxx , safty lane and replace both front tires			tires 283.30 , 2 fronts

# MAINTENANCE CAR REPAIR RECORDS *Mileage 87061*

<b>VEHICLE #</b>	<b>2B</b>	<b>LOCATION</b>	<b>South</b>
<b>YEAR</b>	<b>2008</b>	<b>LICENSE #</b>	<b>M170327</b>
<b>TYPE</b>	<b>Activity Bus</b>	<b>VIN #</b>	<b>1GBJG31K381161017</b>
<b>COLOR</b>	<b>White</b>		

<b>Service Date</b>	<b>Mileage</b>	<b>Repair Description</b>	<b>Part #</b>	<b>Cost</b>	<b>Comments</b>
10/21/2014	54688	heat blower motor, and rear door motor cut out	<b>26-19902</b>	\$93.00	granger 6A886G
3/16/2014	50580	install 8 new tires		\$769.87	just tires
11/20/2014	55190	install front pads , rotors and front hub assy.		614.02	365628 O'reilly, used ceramic pads
1/12/2015	55820	replace both front headlamps and clear code			gas cap loose
5/2/2015	58389	had to refasten the rear head pad by the back	25750064/1038	21.69/25.36	replace the handle and cover assy.
6/11/2015	59495	sevice xxx inspect and fill tires			general inspection
10/22/2015	63173	installed		61.95	Midas did the work
1/21/2016	64797	levels			
4/12/2016	65900	Take to test station for for 6 mo test			30 had to replace rt turn bulb
8/1/2016	67439	install new wiper blades			Find Ok at this time
4/2/2017	68731	instahl the headlight trim ring.			
5/9/2017	69044	levels, instahl a new air filter			also take to saftey lane for sticker
9/10/2017	73702	installed a new starter and 2 new front hubs	br930353,4n51:2, @208.06,		bus would not start
10/25/2017	74250	safety lane test			
1/26/2018	75746	washer fluid check and top off oil and fasten down			
2/1/2018	75875	install new battery and tightin up mirror			had to jump in lot
6/15/2018	78892	service xxx and general inspection			
10/18/2018	80510	safety lane test			
11/9/2018	81336	stop, also installed new front brakes			
2/6/2019	82528	bank 2 02 sensor bad replace and clear code	21059	54.17	
3/20/2019	83133	the cruise switch brake pedal switch replace the	SL886	17.15	
8/10/2019	86070	a/c charge service xxx repair rear door safety light			

# MAINTENANCE CAR REPAIR RECORDS *mileage 84632*

**VEHICLE #** 1B  
**YEAR** 2008  
**TYPE** Activity Bus  
**COLOR** White

**LOCATION** SOUTH  
**LICENSE #** M170329  
**VIN #** 1GBJG31K881161093

Service Date	Mileage	Repair Description	Part #	Cost	Comments
10/9/2014	47007	rear brakes and 6 tires		brakes,185.40	tires, axle gaskets
11/7/2014	48000	Service xxx air filter ,wiper blades & check over			
6/9/2015	52171	service xxx change wipers			general inspection
8/20/2015	53095	cap			
9/21/2015	53431	door catch assy.			check operation ok at this time
10/8/2015	54465	put a tailpipe extension on & vehicle test		61.95	Midas on 75th made it and installed
2/8/2016	57558	Install new battery			old
2/18/2016	57745	Service xxx and a general inspection			check and fill tires , &fluid levels
4/13/2016	58932	Take bus to safety lane		30	ectx
4/19/2016	59320	Replace left front spot mirror lens fell out			
4/22/2016	59158	Replace front pads and rotors		169.07	
8/1/2016	61350	install new wiper blades			blade broke off
8/5/2016	62741	inspection			add 134a to A/c
9/12/2016	62912	plug , check for leak found ok at this time			
11/8/2016	64158	after towing the trailer.			found ok at this time.
2/22/2017	66055	bus was taken to Bill Kay for brake issues		630.13	with wheel sensor
6/14/2017	68990	tensioners		176	the A/C belt was missing
9/19/2017	71128	door catch on , replace rear exhaust hanger check			
10/24/2017	71168	replace backup beeper , and safety inspection			
12/19/2017	73296	Service xxx wiper blades			general inspection
4/18/2018	75823	had to replace the left door arm rest		57.38	arm rest cracked inner and outer
10/11/2018	78917	Service xxx wiper blades and e brake cables			bill kay did cables safety lane